


Quality Assurance Labels

A Quality Assurance label is attached to each piece. The significance of each part of the label is described below.



1. GLTAA Quality Mark.
2. Producers GLTAA Accreditation Number.
3.  Brand Name.
4. Service Class 3.
Denotes suitability for fully exposes areas with EMC above 20%.
5. Appearance Grade A.
Denotes suitability for a clear finish.
6. Mechanical properties grade tested according to AS/NZS 1328
7. Symbol for straight glulam (S) or pre-cambered glulam (C)
8. Denotes the Australian / NZ Standard used to manufacture and test the product.